# CE-1000

quickstart guide

The CE-1000 Small to Medium Meeting Room workplace technology solution includes a Crestron Mercury® Tabletop Conference System Video Package and the cables required to provide a variety of conference room capabilities.

1 Preparation

Verify Contents

Check the table below for the system's package contents before starting installation. The following items are included:

PRODUCT NAME	DESCRIPTION	QUANTITY	PART NUMBER
CBL-HD-20	HDMI® Interface Cable, HDMI, 20 feet (6.1 m)	1	6503567
CBL-HD-THIN-HS-6	HDMI Interface Cable, Thin, Type A Male-to-Male, 6 feet (1.83 m)	1	6508218
CBL-USB-A-EXT-15	USB Extension Cable, Type A Male-to-Female, 15 feet (4.57 m)	1	6508260
CCS-CAM-USB-F-100	Logitech® Webcam C930e	1	6506442
CCS-UC-1-AV	Crestron Mercury Tabletop Conference System, Video Package	1	6508259
PW-2420RU	Power Pack	1	6500187
STIRP	IR Emitter Probe w/3.5 mm Mini Phone Plug	1	6500940

Additional Requirements

- A video display (sold separately) must be connected to the HDMI output.
- A source device (sold separately) can be connected to the CCS-UC-1 with the CBL-HD-THIN-HS-6 and USB 2.0, A-to-micro B cables.

2 Connect the System

CCS-UC-1 (Rear View)

❶ Connect the STIRP to the IR port and mount it on the display device (sold separately).

❷ Connect the CBL-HD-20 cable to the HDMI OUT port and to the display device's HDMI input port.

❸ Connect the CBL-HD-THIN-HS-6 cable to the HDMI IN port and route it to the front of the CCS-UC-1 for connection to a portable computer (not included) as described in the CCS-UC-1 DO Guide (Doc. 7843) at www.crestron.com/manuals.

❹ Connect the USB 2.0, A-to-micro B cable (included with the CCS-UC-1-AV) to the USB B port and route it to the front of the CCS-UC-1 for connection to a portable computer (not included) as described in the CCS-UC-1 DO Guide (Doc. 7843) at www.crestron.com/manuals.

❺ Connect the CCS-UC-1 to earth ground.

❻ Connect a CAT5e cable (included with the CCS-UC-1-AV) from the corporate LAN to the LAN port.

❼ Connect the CBL-USB-A-EXT-15 cable to the Logitech C930E webcam and the USB/CAM port.

❽ Connect the PW-2420RU power pack to the 24V 2.5A port.

3 Apply Power

When all connections are made, apply power to all of the devices in the system.

4 More Information

For more information, refer to the CCS-UC-1 DO Guide (Doc. 7843) and the CCS-UC-1 Supplemental Guide (Doc. 7844) found at www.crestron.com/manuals.

www.crestron.com | 888.273.7876 | 201.767.3400

Specifications subject to change without notice.

CRESTRON®

CE-1000