

Letter of Volatility

April 12, 2021

This letter shows the memory types included in the stated Icron Technologies products. **Note:** User data is not retained if device power is turned off.

Product	Unit	Storage Type	Size	Volatility	Usage	Access Restrictions
USB 3-2-1 Starling 3251C (all Variants)	LEX /REX	IRAM	384kbit	Volatile	Firmware code	Internal firmware access only
		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only
		Cache	694kbit	Volatile	User Data	Internal firmware access only
		Flash	4Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade
		EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade
		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only
		Cache	694kbit	Volatile	User Data	Internal firmware access only
Maverick DisplayPort 1.2a and USB 3-2-1 63104 and 63100 Core	LEX /REX	Flash	4Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade
		EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade
		Data Cache	8kbit	Volatile	Firmware Data	Internal firmware access only
		Flash	264Mbit	Non- volatile	Firmware Code + Configuration Data	Read-only except during firmware upgrade
	LEX /REX	IRAM	896kbit	Volatile	Firmware Code	Internal firmware access only
		DRAM	256kbit	Volatile	Firmware Data	Internal firmware access only
USB 3-2-1 Raven 3104, 3104 Pro, 3124 and 3100 Core		Cache	694Kbit	Volatile	User Data	Internal firmware access only
		Code Cache	8kbit	Volatile	Firmware Code	Internal firmware access only
		Data Cache	8kbit	Volatile	Firmware Data	Internal firmware access only
		Flash	264Mbit	Non- volatile	Firmware Code + Configuration Data	Read-only except during firmware upgrade
VU/EL 5353 DVI + USB 2.0	LEX	IRAM	384kbit	Volatile	Firmware code	Internal firmware access only
		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only
		Cache	694kbit	Volatile	User Data	Internal firmware access only
VU/EL 5363 HDMI + USB2.0		Flash	4Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade
		EEPROM	1Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade



Icron Technologies - Letter of Volatility

ICIOIT TeCHIHOlogies — Lettlet of Volatility							
	REX	EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade	
		IRAM	384kbit	Volatile	Firmware code	Internal firmware access only	
		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only	
		Cache	694kbit	Volatile	User Data	Internal firmware access only	
		Flash	4Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade	
		EEPROM	1Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade	
		EEPROM	2kbit	Non- volatile	Firmware code	Read-only except during firmware upgrade	
		EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade	
		Flash	32kbit	Non- volatile	User Data	Read-only except during firmware upgrade	
		IRAM	384kbit	Volatile	Firmware code	Internal firmware access only	
USB 2.0 Ranger/RG 2301 series		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only	
USB 2.0 Ranger/RG	LEX	Cache	694kbit	Volatile	User Data	Internal firmware access only	
2304 series USB 2.0 Ranger/RG		Flash	4Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade	
2302 USB 2.0 Ranger/RG		EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade	
2311		IRAM	384kbit	Volatile	Firmware code	Internal firmware access only	
USB 2.0 Ranger/RG 2312		DRAM	128kbit	Volatile	Firmware code	Internal firmware access only	
USB 2.0 Ranger/RG		Cache	694kbit	Volatile	User Data	Internal firmware access only	
2324 USB 2.0 Ranger/RG 2344	REX	Flash	4 Mbit	Non- volatile	Firmware code	Read-only except during firmware upgrade	
USB 2.0 RG2300A Core USB 2.0 RG2310A Core		EEPROM	4kbit	Non- volatile	Configuration	Read-only except during firmware upgrade	
USB 2.0 Ranger/RG		IRAM	8192kbit	Volatile	Firmware code	Internal access only	
2201 USB 2.0 Ranger/RG	LEX	DRAM	4096kbit	Volatile	Firmware data	Internal access only	
2204		Cache	8-1024 bytes	Volatile	User Data	Internal access only	
USB 2.0 Ranger/RG 2211		Flash	1Mbit	Non- volatile	Firmware Code	Read-only except during firmware upgrade	
USB 2.0 Ranger/RG 2212		IRAM	8192kbit	Volatile	Firmware code	Internal access only	
USB 2.0 Ranger/RG		DRAM	4096kbit	Volatile	Firmware data	Internal access only	
2224		Cache	8-1024 bytes	Volatile	User Data	Internal access only	



Icron Technologies – Letter of Volatility

Icron Technologies – L	A Maxim Integrated Brand					
USB 2.0 Ranger/RG 2244 USB 2.0 RG2210 Core USB 2.0 RG2220 Core USB 2.0 RG2230 Core USB 2.0 RG2240 Core		Flash	1Mbit	Non- volatile	Firmware Code	Read-only except during firmware upgrade
USB 2.0 Ranger/RG 2101		FPGA	486kbit	Volatile	User Data	Internal Access Only
USB 2.0 Ranger/RG 2104	LEX	SPI Flash	4Mbit	Non- Volatile	Firmware Code	Read-only except during firmware upgrade
USB 2.0 RG2100 Core		CryptoAuthentication Chip	2kbit	Non- Volatile	Authentication	Internal Access Only
		FPGA	486kbit	Volatile	User Data	Internal Access Only
	REX	SPI Flash	4Mbit	Non- Volatile	Firmware Code	Read-only except during firmware upgrade
USB 3.0 Spectra/SP	LEX	Flash	16kbit	Non- Volatile	Firmware Code	Internal Access Only
3022	REX	Flash	16kbit	Non- Volatile	Firmware Code	Internal Access Only
	LEX	Flash	512Byte	Non- Volatile	Firmware Code	Read Only
USB 3.0 Spectra/SP 3001-15	REX	Flash	512Byte	Non- Volatile	Firmware Code	Read Only
	NEA	EEPROM	2kbit	Non- Volatile	Firmware Code	Read Only



Icron Technologies - Letter of Volatility

Toron Toomiologico	ICIOIT Technologies — Letter of Volatifity A Maxim Integrated Brand								
Product	Unit	Storage Type	Size	Volatility	Usage	Access Restrictions			
	LEX	SPI Flash	8Mbit	Non-Volatile	Firmware Code + User Data	Read-only except during firmware upgrade; Internal Access Only			
		IC NAND Flash	1GBit	Non-Volatile	Firmware Code + User Data	Read-only except during firmware upgrade; Internal Access Only			
		SDRAM	1GB	Volatile	User Data	Internal Access Only			
EL3500		SRAM	2Mbit	Volatile	User Data	Internal Access Only			
		Flash	16kBit	Non-Volatile	Firmware Code	Internal Access Only			
EL4500	REX	SPI Flash	8Mbit	Non-Volatile	Firmware Code + User Data	Read-only except during firmware upgrade; Internal Access Only			
		IC NAND Flash	1GBit	Non-Volatile	Firmware Code + User Data	Read-only except during firmware upgrade; Internal Access Only			
		SDRAM	1GB	Volatile	User Data	Internal Access Only			
		SRAM	2Mbit	Volatile	User Data	Internal Access Only			
		IRAM	8192kbit	Volatile	Firmware code	Internal access only			
		DRAM	4096kbit	Volatile	Firmware data	Internal access only			
	LEX	Cache	8-1024 bytes	Volatile	User Data	Internal access only			
		Flash	1Mbit	Non-Volatile	Firmware Code	Read-only except during firmware upgrade			
		EEPROM	1Mbit	Non-Volatile	Firmware Code	Read-only except during firmware upgrade			
	REX	IRAM	8192kbit	Volatile	Firmware code	Internal access only			
EL5100		DRAM	4096kbit	Volatile	Firmware data	Internal access only			
EL5200		Cache	8-1024 bytes	Volatile	User Data	Internal access only			
		Flash	1Mbit	Non-Volatile	Firmware Code	Read-only except during firmware upgrade			
		EEPROM	1Mbit	Non-Volatile	Firmware Code	Read-only except during firmware upgrade			
		EEPROM	2kbit	Non-Volatile	Firmware Code	Read-only except during firmware upgrade			
		Flash	32kbit	Non-Volatile	User Data	Internal Access Only			
USB 1.1 Rover	LEX	CPLD	2kbit	Non-Volatile	Firmware Code	Internal Access Only			
1650/2650	REX	CPLD	2kbit	Non-Volatile	Firmware Code	Internal Access Only			
USB 1.1 Rover	LEX	CPLD	8kbit	Non-Volatile	Firmware Code	Internal Access Only			
1850/2850	REX	CPLD	8kbit	Non-Volatile	Firmware Code	Internal Access Only			
	KEX	OI- LD	OKDIL	Non-voiatile	i iiiiwaie Coue	Internal Access Only			