

Crestron **PW-1205**

Wall-Mount Power Pack 12VDC, 0.5A

Installation Guide



## Regulatory Compliance

This product is Listed to applicable UL Standards and requirements by Underwriters Laboratories, Inc.



As of the date of manufacture, the PW-1205 has been tested and found to comply with specifications for CE marking and Japan electrical appliance and material safety law.



Product warranty can be found at [www.crestron.com/warranty](http://www.crestron.com/warranty).

The specific patents that cover Crestron products are listed at [patents.crestron.com](http://patents.crestron.com).

Crestron and the Crestron logo are either trademarks or registered trademarks of Crestron Electronics, Inc. in the United States and/or other countries. UL and the UL logo are either trademarks or registered trademarks of Underwriters Laboratories, Inc. in the United States and/or other countries. Other trademarks, registered trademarks, and trade names may be used in this document to refer to either the entities claiming the marks and names or their products. Crestron disclaims any proprietary interest in the marks and names of others. *Crestron is not responsible for errors in typography or photography.*

This document was written by the Technical Publications department at Crestron.  
©2014 Crestron Electronics, Inc.

## Description

The PW-1205 is a 500 mA, 12 volt wall-mounted power pack that is included with many Crestron® products. It is designed for indoor use only.

---

**CAUTION:** Connect this power pack to a Crestron device that is rated at 12 volts and no more than 500 mA. Plugging this power pack into a Crestron device that has a different rating could damage the device or the power pack.

---

## Specifications

Crestron suggests using this power pack with designated Crestron products. In the event another compatible power pack (not supplied by Crestron) is required, the specifications are as follows.

### *PW-1205 Specifications*

INPUT	OUTPUT
120 V 60 Hz	12 Vdc 500 mA

The polarity of the PW-1205 is illustrated below.




## Setup

Complete the following steps to connect the power pack.

1. Insert the PW-1205 plug into the dc power input of a Crestron device.
2. Insert the power pack into an active ac outlet.

### ***PW-1205 Power Pack Hookup***

120 Vac Outlet



## **Further Inquiries**

To locate specific information or resolve questions after reviewing this guide, Contact Crestron's True Blue Support at 1-888-CRESTRON [1-888-273-7876] or, for assistance within a particular geographic region, refer to the listing of Crestron worldwide offices at [www.crestron.com/offices](http://www.crestron.com/offices).

To post a question about Crestron products, log onto Crestron's Online Help at [www.crestron.com/onlinehelp](http://www.crestron.com/onlinehelp). First-time users must establish a user account to fully benefit from all available features.



**Crestron Electronics, Inc.**  
15 Volvo Drive Rockleigh, NJ 07647  
Tel: 888.CRESTRON  
Fax: 201.767.7576  
[www.crestron.com](http://www.crestron.com)



**Installation Guide - DOC. 5759B**  
**(2001997)**  
**11.14**

Specifications subject to  
change without notice.