



VCCI Council

## Acceptance of Report of Compliance

**Company name:** Intel K.K.  
**Address:** 東京都千代田区丸の内3-1-1 国際ビル5階  
**Responsible person:** Lillian Li  
**Department:** Corporate Product Regulation Standards  
**E-mail:** lillian1.li@intel.com  
**Contact person:** Lillian Li  
**Address:** 2200 Mission College BLVD, Santa Clara CA 95054  
**Department:** CISD  
**Phone:** 5036962691  
**FAX:** 5036962349  
**E-mail:** lillian1.li@intel.com  
**Member number:** 338  
**Report No.:** 2018066869  
**Reporting date:** 2018/05/18  
**Reporting media:** online  
**Status:** accepted  
**Last report No.:**  
**Acceptance No.:** 2018046923  
**Sub No.:** 1  
**Acceptance date:** 2018/05/18  
**Recipient of Acceptance Notice:**  
**Department:** Corporate Product Regulation Standards  
**E-mail:** lillian1.li@intel.com

Reporting type:	new		
Applied VCCI Rule:	VCCI 32-1		
Classification of Equipment and classification code:	ClassB / Classification code b2		
General Name of Equipment:	Intel NUC		
Product type (Model No.):	xNUC8xBEKx; xNUC8xBEHx		
Member number of a test laboratory:	237	Audix Technology Corporation	
Name of the testing laboratory:			
Measurement facility registration number:	Done		Measurement distance
	1) Radiated EMI measurement below 1GHz facility	R-3918	10 m
	2) Radiated EMI measurement above 1GHz facility	G-10628	3 m
	3) Mains port conducted EMI measurement facility	C-4426	
	4) Wired network port and other port Conducted EMI measurement facility	T-1411	
	5) Article 15 registered laboratory	A-	
	6) This compliance verification test was conducted at the installation site of users.		
Date of testing:	2018/03/23 3/23/2018 - 3/26/2018		
Serial No. of the test report:	EM-V180034; EM-V180040		
Reason for addition/modification:			
VCCI comment:			